SCHOOL NAME: Cootes Paradise

					Time to Complete Check	Requires Immediate Attention to Maintain		
Unit Type and Tag	Model	Serial Number	Unit Location	Serves		Ventilation (Y/N)	Materials	Comments
UV	AAF 40021000	89F4891	rm124	rm 124	30	N	1-12X48X1 pltd	ok
UV	AAF 40021000	unknown	rm125	rm 125	30		1-12X48X1 pltd	ok
UV	AAF 40021000	89F4892	rm225	rm225	30	Ν	1-12X48X1 pltd	ok
UV	AAF 40021000	unknown	rm224	rm224	30	Ν	1-12X48X1 pltd	ok
SF supply fan	sheldon		basement mech	west side school	45	Y	2-B257 4-20X30X1 pltd	not operating
SF supply fan	sheldon		basement mech	east side school	45	Y	2-B122 4-22X30X1p pltd 4-24X30X1 pltd	needs belts, not operating, diificult location
RTU4	LGH060H4EU2J lennox	5614H07892	roof west	west side school	45		4-20X20X2 pltd	
RTU2	LGH048H4EU2J lennox	5614H07891	roof west	west side school	45	Y	4-16X20X2 pltd	evap coil needs cleaning
							1-BX59	
RTU3	LGH15054BM4J lennox	5614HO6766	roof west	west side school	45		4-20X25X2 pltd	econo filters broken and plugged
RTU1	LGH156H4BS2J lennox	5614HO8120	roof west	west side school	45	Y	1-B64 6-20X24X2 pltd	unit not operating , needs belt badly, coil dirty as filters are missing(try 2-12x24x2)
EF	Penn domex	AQ24	roof west	west side school	15			barometric dampers out and on roof
EF	Penn domex	XRF94	roof west	west side school	15	Y		barometric dampers out and on roof
RTU trane	YSC048A trane	207100874L	centre high roof	centre	45	Y	2-20X25X1 pltd 1-AX26	needs belt and secure panels
MUA2	TBA250 airwise	MUA2	centre high roof	centre	45	Y	1-B53 2-24X24X2 pltd	unit has not run in a while pulleys all rusted
RTU trane	YSC048A trane	207100871L	centre high roof	centre	45	Y	1-AX26 2-20X30X1 pltd	need belt and clean evap coil
MUA1	TBA400 airwise	MUA1	centre high roof	centre	45		1-B53 3-20X24X2 pltd	unit has not run in a while pulleys all rusted
EF (large fan)	sheldon		centre high roof	centre west	15		2-B180	not operating difficult access
EF (large fan)		500000	centre high roof	centre east	15			door broken on roof could not get in
VRF	Daikin R2R36PVJV	E000322	centre high roof	office	15			
VRF	Daikin R2R36PVJV	E000387	centre high roof	office	15			
RTU5	LGH036H4EU2J lennox	5614H07893	east roof	east side school	45		4-16X20X2 pltd 1BX75 2-20X24X2 pltd 2-16X24X2 pltd	clean evap coil 1 belt missing and fallen down duct
AHU1	DJX600 eng air	S51575AHU1	east roof	east side school	45		return belt missing	replace supply belt
EF EF	GB0814XQDR2 GB0070DGEXQD	14692	532 east roof 843 east roof	east side school east side school	15		1-3L190	needs belt